

### HOY CREEK, COQUITLAM BC

Section 2
Feature 19 –
Concern for
juvenile passage at
low flow



Section 2
Feature 24 – Log
jam, potential
barrier





Section 3
Feature 39 – small debris jam, possible barrier during low flows.



Section 3
Feature 46 –
Culvert.
Installation of
baffles in one
culvert would
provide to adult and
juvenile salmon.







Section 3
Feature 53 – Low flows may impede juvenile passage



Section 3
Feature 81 – Log
Jam Barrier.



Fraser Salmon & Watersheds Program







Section 3
Feature 94 –
Concern is adult migration during low flow.



Section 3
Feature 100 – LWD
jam. Requires
adjustment for
passage.





Section 4
Feature 126 – LWD jam. Requires maintenance to improve passage.



Section 4
Feature 131 – Log
jam barrier.
Presently a barrier.





Fraser Salmon & Watersheds Program







Section West Hoy Feature 3 – Log jam. Presently a barrier and requires maintenance.



Section West Hoy
Feature 4 – Log
jam. Small amount
of debris removal
would create access.

