



Impediments to Fish Passage

Fraser Salmon & Watersheds Program



Fraser Basin Council



MAPLE CREEK, COQUITLAM BC

Section 1

Feature 4 – Flood gate



Section 1

Feature 6 – Small woody debris





Impediments to Fish Passage

Fraser Salmon & Watersheds Program



Fraser Basin Council



Section 2
Feature 32 – CPR
habitat pond.
Beavers blocking
flow.



Section 2
Feature 33 –
Culvert under CPR
tracks. Baffles
required.





Impediments to Fish Passage

Fraser Salmon & Watersheds Program



**Section 3
Feature 41 – Twin
box culvert. Gated
with 1” bars. Right
bottom culvert bar
removed for fish
passage.**



**Section 3
Feature 45 –
Concrete weir.
Monitor for
blockages.**





Impediments to Fish Passage

Fraser Salmon & Watersheds Program



Fraser Basin Council



**Section 3
Feature 49 – Log
jam. Remove one
side of debris
barrier.**



**Section 3
Feature 53 –
Culvert. No passage
past this point.**





Impediments to Fish Passage

Fraser Salmon & Watersheds Program



Section 3
Feature 75 –
Fencing crossing.
Potential
obstruction.



Section 4
Feature 104 –
Blocked culvert

